



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

### Minerals Regulatory Program

Report Date: April 3, 2007

Supervisor MOZ

**Mine Name:** Nichols Pit  
**Operator Name:** Western Rock Products  
**Bob Roth**  
**820 North 1080 East**  
**St George, Utah 84770**

**Permit number:** M/021/039  
**Date:** February 12, 2007  
**Time:** 12:15 PM

**Inspector(s):** Doug Jensen, Daron Haddock

**Other Participants:** None

**Mine Status:** Active

**Weather:** mild, sunny

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Checked the quarry site while in the area.

#### Directions to Site:

The site is located approximately 9 miles west of Cedar City along the Lund highway. Turn right on Iron Springs road. Turn right on Sage Hills drive and go across RR tracks to site.

#### Inspection Summary:

The site was inactive at the time of this inspection. No equipment was on site and no mining was occurring. A large stockpile of crusher material is still located on the pit floor.

The site appeared stable with no notable environmental concerns.

#### Conclusions and Recommendations:

Continue to monitor the site when in the area.

**Inspector's Signature** Daron G. Haddock

**Date:** 4/3/07

dj:pb

cc: Western Rock Products

P:\GROUPS\MINERALS\WP\M021-Iron\M0210039-WesternRock\inspections\02122007insp.doc